

DATE 1931Z 15 NOV 61

~~TOP SECRET~~

ROUTING	
1	4
2	5
3	6

OPERATIONAL IMMEDIATE

OPERATIONAL IMMEDIATE

TO : DIRECTOR
FROM : [REDACTED] 25X1C
ACTION: OPS (1-2-3-4-5)
INFO : S/C (6)

WLM

TOR: 1915Z 15 NOV 61

IN 22555

TO OPIM [REDACTED] 25X1C

INFO

CITE

9167

25X1C

25X1C

A. 1082.

B. [REDACTED] 15/1853Z.

25X1C

C. GOOD.

D. GOOD.

E. AC ALTERNATOR FAILURE.

F. NONE.

G. A/C ALTERNATOR FAILED. PILOT OBSERVED SMOKE FROM ENGINE

AREA VENTS. BELIEVED CAUSED FROM ALTERNATOR FAILURE. PRELIMINARY

INSPECTION IN WHEEL WELL INDICATES A/C ALTERNATOR WIRING CHARRED.

WILL ADVISE FURTHER DETAILS WHEN AVAILABLE. [REDACTED] ENGINEER

INVESTIGATING PROBLEM.

25X1C

END OF MESSAGE

DOCUMENT NO. _____
NO CHANGE IN CLASS. ☐
☐ DECLASSIFIED
CLASS. CHANGED TO: TS (S) C
NEXT REVIEW DATE: _____
AUTH: HR 10-2
DATE: 29 Oct 86 REVIEWER: [REDACTED]

~~TOP SECRET~~

25X1A